

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

PRAIRIE CREEK FISH HATCHERY

HAER CA-334

Redwood National Park

Hwy. 101

Orick

Humboldt County

California

## INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jet Lowe, photographer, September 2005

CA-334-1	Hatchery complex looking northwest by 295 degrees.
CA-334-2	Hatchery complex looking northwest by 305 degrees.
CA-334-3	View looking northwest of the main hatchery building with the tank in the foreground. View to the southeast.
CA-334-4	Perspective view, Exterior of main hatchery building looking east, northeast.
CA-334-5	Perspective view, Exterior of main hatchery building. View to the west, northwest.
CA-334-6	Perspective the office, interior of main hatchery building. View to the northwest.
CA-334-7	Perspective of laboratory, interior of main hatchery building. View to southwest.
CA-334-8	Perspective of tool room, interior of main hatchery building. View to the southwest.
CA-334-9	Perspective view of interior main hatchery building, view to west.
CA-334-10	Perspective of rearing tanks and work trays, interior of main hatchery building. View to southeast.

PRAIRIE CREEK FISH HATCHERY  
HAER CA-334  
INDEX TO PHOTOGRAPHS

CA-334-11	Perspective view of interior of the main hatchery building. View to the northwest.
CA-334-12	View of foot of troughs showing signs/placards. Interior of main hatchery building, view northwest.
CA-334-13	Detail view of troughs, pumps and screens, interior of main hatchery building. View to the west.
CA-334-14	Detail of pumps in troughs, detail of truss - attachment to the wall - as well as the troughs themselves. Interior of the main hatchery building, view to the east.
CA-334-15	Perspective view of the interior main hatchery building, view to the northeast.
CA-334-16	Detail of trough as well as interior wall construction in main hatchery building. View to the northwest.
CA-334-17	Detail of interior truss, main hatchery building. View to the east.
CA-334-18	Superintendent's quarters with pump house in the foreground and the hatchery in the background. View to the northwest.
CA-334-19	Superintendent and assistant superintendent's quarters with the tank in the foreground. View to the southeast.
CA-334-20	Perspective of the superintendent's house, assistant superintendent's house, and pump house near Highway 101. View to the northeast.
CA-334-21	Perspective of the exterior of the assistant superintendent's house with the superintendent's house in the background. View to the west, southwest.
CA-334-22	Shed and garage, perspective shot, view to the northwest.
CA-334-23	Perspective of the garage. View to the north.
CA-334-24	Perspective view of the pump house looking south 180 degrees. This is the pump house at the southern most point of the complex.
CA-334-25	Interior detail of pump house (1962) at southern most point of the complex.

PRAIRIE CREEK FISH HATCHERY  
HAER CA-334  
INDEX TO PHOTOGRAPHS

CA-334-26	Pump house adjacent to the superintendent's house at the west end of the complex near Highway 101. Detail of Holloshaft pump. View to the south.
CA-334-27	Pump for spawning channels includes a turbine and motor. Turbine is Berkeley H-17500, model 8C2PH, Serial No. 2889, B. M. No. 4886 - Berkeley Pump Co. The Motor is G.E. Induction Motor, model 5K4256XA3YL, serial no. GAJ728337, Tri-Clad. View looking northeast.
CA-334-28	Elevation shot of spawning channels at southern entrance of complex. View to the west.
CA-334-29	Detail of spawning channels at south end of complex near entrance. Pump house in background. View to the southeast.
CA-334-30	Cement tank feature with Assistant's quarters in the background. View to the northwest.
CA-334-31	Elevation shot of large rectangular rearing tanks (pair). Warehouse in the background. View to the north.
CA-334-32	Detail of gate, gate slots, and connection between the two segments of the rectangular rearing tank. Pump house (1962) at entrance is in the background. View to the southwest.
CA-334-33	Detail of ump that is attached to rectangular rearing tanks (pair). Pump located on the north end of rearing tank. View to the northwest.
CA-334-34	Perspective circular rearing ponds on north side of hatchery. View to the west, northwest. Includes view of ditch and step up to hatchery building on left side of image.
CA-334-35	Aeration tower/pump. View to the north.